



**CW-90/CW-90X**

CW-90




CW-90X

**Part Number/Price**

| Ref#                     | Part#         | Description                              | Price   |
|--------------------------|---------------|------------------------------------------|---------|
| <b>CW-90X Load Cells</b> |               |                                          |         |
|                          | <b>107174</b> | RLPWM15HE 10 kg (5 lb and 10 lb scale)   | Consult |
|                          | <b>107175</b> | RLPWM15HE 20 kg (25 lb scale)            | Consult |
|                          | <b>107176</b> | RLPWM15HE 50 kg (50 lb scale)            | Consult |
|                          | <b>107177</b> | RLPWM15HE100 kg (100 lb scale)           | Consult |
| <b>CW-90 Load Cells</b>  |               |                                          |         |
|                          | <b>107756</b> | RL1040 7 kg (5 lb scale)                 | Consult |
|                          | <b>107757</b> | RL1040 10 kg (10 lb scale)               | Consult |
|                          | <b>107758</b> | RL1040 30 kg (25 lb scale)               | Consult |
|                          | <b>107759</b> | RL1040 50 kg (50 lb scale)               | Consult |
|                          | <b>107760</b> | RL1040 100 kg (100 lb scale)             | Consult |
|                          | <b>107476</b> | Bench scale foot                         | Consult |
|                          | <b>106101</b> | Assembled CPU and display board          | Consult |
|                          | <b>105555</b> | Coupling nut for feet and overload stops | Consult |
|                          | <b>105945</b> | Parts kit, CW-90/90X (1)                 | Consult |
| 3                        | <b>14621</b>  | Nut, Kep 6-32 NC hex (2)                 | Consult |
| 4                        | <b>85202</b>  | Power cord assembly, 120VAC (1)          | Consult |
| 4                        | <b>85203</b>  | Power cord assembly, 230VAC (1)          | Consult |
| 5                        | <b>68600</b>  | Cord grip, PG11 (1)                      | Consult |
| 6                        | <b>68599</b>  | Seal ring, nylon PG11 (1)                | Consult |
| 7                        | <b>68601</b>  | Nut, PG11 (1)                            | Consult |
| 8                        | <b>58983</b>  | Cable grip, SL-7 with nut (3)            | Consult |
| 9                        | <b>16892</b>  | Label, earth ground (1)                  | Consult |
| 10                       | <b>15134</b>  | Washer, Lock no. 8 type A (3)            | Consult |
| 11                       | <b>14626</b>  | Nut, Kep 8-32 NC hex (3)                 | Consult |
| 12                       | <b>45043</b>  | Wire, ground 4 in W/No.8 (1)             | Consult |
| 13                       | <b>104914</b> | Overlay, membrane switch (CW-90)         | Consult |
| 13                       | <b>104915</b> | Overlay, piezo (CW-90X)                  | Consult |
| 15                       | <b>212841</b> | Power supply, switching (1)              | Consult |
| 16                       | <b>14822</b>  | Screw, MACH 4-40 NC x 1/4 (6)            | Consult |
| 17                       | <b>14825</b>  | Screw, MACH 4-40 NC x 1/4 (4)            | Consult |
| 18                       | <b>105976</b> | Cable assembly, power supply (1)         | Consult |
| 19A                      | <b>102354</b> | CPU (1) (battery p/n 69291 not included) | Consult |
| 19A                      | <b>120084</b> | CPU CW-90, with battery                  | Consult |
| 19B                      | <b>105741</b> | Display (1)                              | Consult |
| 20                       | <b>69291</b>  | Battery, 3V coin lithium (1)             | Consult |
| 21                       | <b>42640</b>  | Screw, MACH 1/4-28 NF X 1/4 (1)          | Consult |
| 22                       | <b>44676</b>  | Washer, bonded sealing (1)               | Consult |
| 24                       | <b>84388</b>  | Gasket, backplate 420 (1)                | Consult |
| 25                       | <b>222569</b> | Vent, breather sealed (1)                | Consult |
| 26                       | <b>182480</b> | Nut, breather vent (1)                   | Consult |
| 27                       | <b>14862</b>  | Screw, MACH 8-32 NC x 3/8 (4)            | Consult |
| 28                       | <b>45042</b>  | Washer, bonded sealing SST (4)           | Consult |
| 29                       | <b>29635</b>  | Stand, tilt SST (1)                      | Consult |
| 30                       | <b>103988</b> | Washer, nylon .52 10 x (2)               | Consult |
| 31                       | <b>103610</b> | Knob, black 1/4-20 (2)                   | Consult |
| 34                       | <b>16861</b>  | Label, warning high (1)                  | Consult |

(See Diagram CW-90/90X)

CHECKWEIGHERS  
**CW-90/CW-90X**



*CW-90/90X Indicator*