

Ishida Uni-10

Printer Unit, Bench/Pole




Part Number/Price

Ref #	Part #	Description	Qty	Synonym	Price
1	Consult	Frame printer	1	400-000-5880-00	Consult
2	Consult	Frame, printer: upper	1	400-000-7264-00	Consult
3	223780	Bracket, sensor, peel, emitter	1	400-000-7265-00	Consult
4*	171877	Sensor, peel, emitter	1	400-000-7266-00	Consult
5	Consult	Accessory, clamp: wire	6	400-000-7267-00	Consult
6*	87532	Sensor, cassette number	1	400-000-7268-00	Consult
7	Consult	Catch, support	1	400-000-7269-00	Consult
8	175360	Catch, roller	1	400-000-7270-00	Consult
9	Consult	Accessory, clamp: ckn clamp	1	400-000-7271-00	Consult
10	223781	Spur gear, take motor	1	400-000-5904-00	Consult
11*	119168	Motor, stepping	1	000-089-5513-01	Consult
12	223782	Accessory, clamp: flat cable	1	400-000-7272-00	Consult
13*	171876	Peel sensor, transmitter, lower left	1	400-000-7273-00	Consult
14	Consult	Cover, harness, thermal	1	400-000-7274-00	Consult
15	Consult	Sheet, cover, harness	1	400-000-7275-00	Consult
16	Consult	Shaft, printer	1	400-000-7276-00	Consult
17	223785	Accessory, clamp, flat cable	1	400-000-7277-00	Consult
18	163272	Bracket, printer	1	400-000-7278-00	Consult
19	223787	E ring, SST	2	400-000-0969-00	Consult
20	185707	Rail, printer left	1	400-000-7279-00	Consult
21	174991	Bushing	2	400-000-7280-00	Consult
22	185711	Spring, coil	1	400-000-7281-00	Consult
23	185710	Rail, printer right	1	400-000-7282-00	Consult
24	46989	Collar, spacer	1	400-000-7283-00	Consult
25	195128	Stopper	1	000-089-5127-06	Consult
26	175486	Collar, spacer	2	400-000-7284-00	Consult
27	115169	Collar, spacer	2	400-000-7285-00	Consult
28	Consult	Stay, head, thermal	1	400-000-7286-00	Consult
29	47215	C ring, for shaft, M6 SST	3	400-000-7193-00	Consult
30	96437	Plate A, spring: support	1	400-000-7287-00	Consult
31	96436	Spring, compressive coil	2	400-000-7288-00	Consult
32	96435	Spring, compress coil	1	400-000-7289-00	Consult
33	96440	Cover, head	1	400-000-7290-00	Consult
34	96434	Bracket, head	1	400-000-7291-00	Consult
35*	171875	Print head, thermal	1	400-000-7292-00	Consult
36*	87533	Label gap sensor	1	400-000-7293-00	Consult
37	Consult	Press as: label sensor	1	400-000-7294-00	Consult
38	206368	Set screw, M3-0.5 × 3 mm, cup point	2	400-000-5821-00	Consult
39	115168	Plate A: sq	1	400-000-7295-00	Consult
40	199792	Pan head screw, M3 × 5, flange washer, SST	2	400-000-7296-00	Consult
41	48240	Cross pan head screw, M3 × 8, SST	2	400-000-5343-00	Consult
42	200524	Cross pan head screw, with SW, M4 × 10, zinc	4	400-000-5377-00	Consult
43	48784	Pan head tapping screw, M3 × 6, SST	2	400-000-7297-00	Consult
44	42728	Pan head tapping screw, M4 × 6, flange washer SST	4	400-000-7298-00	Consult
45	42851	Cross truss screw, M4 × 10, button head, SST	2	400-000-7299-00	Consult
46	47008	Pan head tapping screw, M4 × 6, flange washer zinc	2	400-000-7300-00	Consult
47	185713	Cross pan head screw with thread lock, M4 × 12, SST	1	400-000-7301-00	Consult
Additional Parts Available					
	Consult	Printer unit, complete, pole	1	400-000-6635-00	Consult
	226054	Printer unit, complete, bench	1	400-000-5918-00	Consult

*See Wiring Diagram on page 79

Ishida Uni-10

Printer Unit, Bench/Pole



Price Computing
Printing Scales