

Ishida Uni-10

Wiring Diagram, 12.1 Inch, Bench/Pole



Part Number/Price

Ref #	Part #	Description	Qty	Synonym	Price
Bench					
1*	221033	Harness, C2, thermal head	1	400-000-5804-00	Consult
2*	221034	Harness, C6, LCD, operator display	1	400-000-5814-01	Consult
3*	221035	Harness, S2, power supply to CPU board	1	400-000-5809-00	Consult
4*	221036	Harness, C5 sensors (cassette no., peel, gap)	1	400-000-5810-01	Consult
5*	221037	Harness, C4, printer motor	1	400-000-5811-00	Consult
6*	221038	Harness, S2, power switch	1	400-000-5812-00	Consult
7*	221040	Harness, C4, LCD, customer display	1	400-000-5813-00	Consult
8*	221041	Harness, C3, CPU board to A/D board	1	400-000-5815-00	Consult
9*	125707	Fuse: glass tube, 250V, 6A	1	400-000-7263-00	Consult
10*	Consult	Ferrite core CU1530G	1	400-000-5800-00	Consult
11*	Consult	Ferrite core CU0730G	2	400-000-5801-00	Consult
12*	Consult	Ferrite core	2	000-089-6532-05	Consult
Pole					
2*	221034	Harness, C6, LCD, operator display	1	400-000-5814-01	Consult
3*	221035	Harness, S2, power supply to CPU board	1	400-000-5809-00	Consult
4*	221036	Harness, C5 sensors (cassette no., peel, gap)	1	400-000-5810-01	Consult
5*	221037	Harness, C4, printer motor	1	400-000-5811-00	Consult
6*	221038	Harness, S2, power switch	1	400-000-5812-00	Consult
8*	221041	Harness, C3, CPU to A/D board	1	400-000-5815-00	Consult
9*	125707	Fuse: glass tube, 250V, 6A	1	400-000-7263-00	Consult
10*	Consult	Ferrite core CU1530G	1	400-000-5800-00	Consult
11*	Consult	Ferrite core CU0730G	2	400-000-5801-00	Consult
12*	Consult	Ferrite core	2	000-089-6532-05	Consult
13*	175676	Ferrite core CU1330B	1	000-089-6531-01	Consult
15*	224133	Harness, C2, thermal head	1	400-000-6873-00	Consult
16*	224134	Harness, C4, LCD customer display	1	400-000-6638-00	Consult

*See Wiring Diagram on page 79

Ishida Uni-10

Wiring Diagram, 12.1 Inch, Bench/Pole

