

Uni-10H

Wiring Diagram, Hanging




Part Number/Price

Ref #	Part #	Description	Qty	Synonym	Price
1*	221033	Harness, C2, thermal head		400-000-5804-00	Consult
2*	221034	Harness, C6, LCD, operator display		400-000-5814-01	Consult
3*	221035	Harness, S2, power, PS to CPU		400-000-5809-00	Consult
4*	221036	Harness, C5, sensors (cassette no., peel, gap)		400-000-5810-01	Consult
5*	221037	Harness, C4, printer motor		400-000-5811-00	Consult
6*	221038	Harness, S2, power switch		400-000-5812-00	Consult
7*	221040	Harness, C4, LCD, customer display		400-000-5813-00	Consult
8*	221041	Harness, C3, scale, CPU to A/D board		400-000-5815-00	Consult
9*	125707	Fuse, glass tube FGA0-2, 6.4 × 30, UL		400-000-7263-00	Consult
10*	Consult	Ferrite core CU1530G		400-000-5800-00	Consult
11*	Consult	Ferrite core CU7030G		400-000-5801-00	Consult
12*	Consult	Ferrite core		000-089-6532-05	Consult

*See Wiring Diagram on page 89

Uni-10H

Wiring Diagram, Hanging



Price Computing
Printing Scales