

Ishida Uni-10H

Printer, Hanging




Part Number/Price

Ref #	Part #	Description	Qty	Synonym	Price
1	Consult	Frame printer	1	400-000-5885-00	Consult
2	Consult	Frame: printer: upper	1	400-000-7264-00	Consult
3	223780	Bracket, sensor, peel emitter	1	400-000-7265-00	Consult
4*	171877	Peel sensor, receiver, upper right	1	400-000-7266-00	Consult
5	Consult	Accessory: clamp: wire	1	400-000-7267-00	Consult
6*	87532	Sensor assembly, cassette number	6	400-000-7268-00	Consult
7	Consult	Catch: support	1	400-000-7269-00	Consult
8	175360	Catch: roller	1	400-000-7270-00	Consult
9	Consult	Accessory: clamp: ckn clamp	1	400-000-7271-00	Consult
10	223781	Spur gear, take motor	1	400-000-5904-00	Consult
11*	119168	Motor: stepping	1	000-089-5513-01	Consult
12	223782	Accessory: clamp: flat cable	1	400-000-7272-00	Consult
13*	171876	Peel sensor, transmitter, lower left	1	400-000-7273-00	Consult
14	Consult	Cover: harness: thermal	1	400-000-7274-00	Consult
15	Consult	Sheet: cover: harness	1	400-000-7275-00	Consult
16	Consult	Shaft: printer	1	400-000-7276-00	Consult
17	223785	Accessory: clamp: flat cable	1	400-000-7277-00	Consult
18	163272	Bracket: printer	1	400-000-7278-00	Consult
19	46986	E ring, SST	2	400-000-0969-00	Consult
20	185707	Rail, printer, left	1	400-000-7279-00	Consult
21	174991	Bushing	2	400-000-7280-00	Consult
22	185711	Spring: coil	1	400-000-7281-00	Consult
23	185710	Rail, printer, right	1	400-000-7282-00	Consult
24	46989	Collar: spacer	1	400-000-7283-00	Consult
25	195128	Stopper	1	000-089-5127-06	Consult
26	175486	Collar: spacer	2	000-005-0812-04	Consult
27	115169	Collar: spacer	2	400-000-7285-00	Consult
28	Consult	Stay: head: thermal	1	400-000-7286-00	Consult
29	47215	C ring, for shaft, M6 SST	3	400-000-7193-00	Consult
30	96437	Plate A: spring: support	1	400-000-7287-00	Consult
31	96436	Spring: coil: compressive	2	400-000-7288-00	Consult
32	96435	Spring: coil: compress	1	400-000-7289-00	Consult
33	96440	Cover: head	1	400-000-7290-00	Consult
34	96434	Bracket: head	1	400-000-7291-00	Consult
35*	171875	Print head, thermal, TPH80R21C	1	400-000-7292-00	Consult
36*	87533	Sensor, label gap	1	400-000-7293-00	Consult
37	Consult	Press assembly, label sensor	1	400-000-7294-00	Consult
38	206368	Set screw, M3-0.5 × 3 mm, cup point	2	400-000-5821-00	Consult
39	115168	Plate A, square	1	400-000-7295-00	Consult
40	199792	Screw, pan head, M3 × 5, flange washer head, SST	2	400-000-7296-00	Consult
41	48240	Screw, cross pan head, M3 × 8, SST	2	400-000-5343-00	Consult
42	200524	Screw, cross, pan head, with SW, M4 × 10, zinc	4	400-000-5377-00	Consult
43	48784	Tapping screw, M3 × 6 pan head, SST	2	400-000-7297-00	Consult
44	42728	Tapping screw, M4 × 6 pan head flange washer, SST	4	400-000-7298-00	Consult
45	42851	Screw, cross truss M4 × 10 button head SST	2	400-000-7299-00	Consult
46	47008	Tapping screw, M4 × 6 pan head flange washer, zinc	19	400-000-7300-00	Consult
47	185713	Screw, cross pan head, with glue, M4 × 12 pan head SST	1	400-000-7301-00	Consult
Additional Parts Available					
	226043	Printer unit, complete, hanging	1	400-000-5919-00	Consult

*See Wiring Diagram on page 89

Ishida Uni-10H

Printer, Hanging



Price Computing
Printing Scales